

**Innovation Central**

10 John Williams Boulevard South, Central Park, Darlington, DL1 1BF
+44 (0) 1325 353776

support@pukka-j.com www.pukka-j.com

Release Notes

Pukka-J DICOM Explorer 6.5.9

(Released 23/09/2025)

Group 2 DICOM Tags in Transfer

It was found that a system was sending group 2 tags [0x0002][0x0017] and [0x0002][0x0018] in a DICOM transfer at the start of the header. This could cause an issue reading the file after saving to disk. The tags are now handled when reading the header.